

NEW-COMP-BJ-MITSUBISHI-LANCERMKVICKPA

ball-joint for MITSUBISHI LANCER MK VI (CK/P_A) | Category: ball-joint | Brand: SLOOP

OE Cross-Reference

OEM BRAND	REFERENCE NUMBERS
OEM	4110A047 4110A048 4110A079 MB856435 MB856436

Vehicle Fitment

MAKE	MODEL	YEARS	POSITION
Mitsubishi	Lancer Mk Vi (Ck/P_a)	—	—

Specifications

Car Brand: MITSUBISHI

Missing Category: ball-joint

Source: wave141-competitor-gap

Competitor Oe Count: 13

Car Model: LANCER MK VI (CK/P_A)

Reason: competitor_gap_import

Cross Refs: 0420CT9R,4110A047,4110A048,4110A079,MB856435,MB856436,M

Discovered At: 2026-05-06

Manufacturer

Sloop Spare Parts Mfg. Co., Ltd. — Taichung, Taiwan, established 1984.

ISO 9001:2015 certified. sloopweb@ms76.hinet.net